

KDM30 Instruction Manual

For Battery / External Power Supply / RS232C



! CAUTION


Please use spanner / wrench when install / remove KDM30.

Installing / removing KDM30 by screwing KDM30 body causes product break.




Flexible Display

Neck rotation angle: Max 330°




(front)

Display rotation angle: Max 330°




■ Explanation of the operation Button & Monitor




Item	Function	How to operate
	Power ON/OFF	ON : Press the Power/Set button . OFF : Press the Power/Set button(≥ 3 sec) .
	Backlight ON/OFF	Press the Power/Set button , and the backlight is turned on . Press the Power/Set button again , and the backlight is turned off .
	Mode change	Press the Power/Set button , and you can switch to the another mode .
	Calling up the setting M1 and M2	M1 : Press the Mode and Set button simultaneously M2 : Press the Shift button during the mode M1
	Monitor display/output of the pressure value	Press the Shift button shortly during the normal measurement , the instantaneous value of the pressure is displayed and output (recorded on the monitor software side) .
	Changing the digit of the setting value	In case that you want to change the digits of the setting value , press the Shift button .
	Selection of the setting item	In case that you choose one of the two , press the Up button .
	Changing of the setting value	Press the Up button in case of changing of the setting value , and you can change the setting value .
	Zero-point correction	Performed electronically by pressing the zero button
	Clearing of peak/valley values	Press the Zero button shortly , and the peak/valley value data recorded is clear .
	Battery remaining amount display	Battery is not needed to replace . Battery is needed to prepare the replacement battery . Battery shud be replaced immediately . (caution) <ul style="list-style-type: none"> • If the battery run out of power , the data of the peak/valley value is not recorded . • The battery recommended replacement time(Battery model : 006P alkali battery) ex) Sampling time : 2 sec • • for about 3 months Sampling time : 0.1sec • • for about 1-2 days
	Insufficient supply voltage display	batt.L is displayed when the supply voltage is shortage .
	Comparing to the level of measurement values (High)	When the measurement value is higher than the setting value " Hi " , the digital display flush " Hi " .
	Comparing to the level of measurement values (Low)	When the measurement value is lower than the setting value " Lo " , the digital display flush " Lo " .
	Peak / Valley display	When the peak or valley value is set , PK is displayed .
	Mode 1	Mode 1 function (see the Page 3 "Mode 1 Parameter table")
	Mode 2	Mode 2 function (see the Page 4 "Mode 2 Parameter table")

■ Mode1 Parameter table



■ Mode2 Parameter table



■ User scale setting procedure


- (1) If you want to use the user scale, set to and proceed to the scale setting.
If you do not use the user scale, it will automatically return to the factory scaling.
- (2) Setting the decimal point position ... Set the decimal point to the required position.
- (3) Zero scale setting ... Enter the value you want to display when the minimum value of the pressure gauge is reached.
- (4) Full scale setting ... Enter the value you want to display when the maximum value of the pressure gauge is reached.
- (5) Negative scale setting ... Enter the value you want to display when the maximum negative value of the pressure gauge is reached.
* Displayed only when coupled pressure is applied.
* If not applicable, enter 0000 or the same value as the zero scale value.
- (6) Unit selection... Select a unit. Select blank (none) if you do not want to display it.
- (7) Select the pressure type. (G: gauge pressure, A: absolute pressure) Select blank (none) if not displayed.

Example) When scaling to 0-1543 (kN) for a gauge pressure of 0-10 (MPa), set as follows.

* Since the unit kN is not in the menu, set a blank (none) for the unit and attach a sticker such as Tepla to the LCD separately.


[Pressure value] [Conversion value]

10.00MPa	⇒	1543kN
0MPa	⇒	0kN




■ Input / output connection example (External 24VDC power supply)


- 4-20mA current output



- 1-5VDC voltage output



- RS232C output




■ Input / output connection example (External AC100V adapter power supply)




Please make a ground (Earth) connection when using the AC100V power adapter.
When using the power adapter AC100V, If the displayed value fluctuates or deviates from the accuracy, Pin 8 connect to ground (Earth).


- 4-20mA current output



- 1-5VDC voltage output




- RS232C output




■ Input / output connection example (Hi / Go / Lo Comparative output)

- External 24VDC power supply / RS232C output



- External AC100V power supply / RS232C output



*The design and specifications are subject to change without prior notice for product improvement.



KRONE CORPORATION

<https://www.krone.co.jp>

Head office
TEL+81-3-3695-5431
FAX+81-3-3695-5698
Email : sales-tokyo@krone.co.jp

Osaka branch
TEL+81-6-6361-4831
FAX+81-6-6361-9360
Email : sales-osaka@krone.co.jp